


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. S-9

History of original corner establishment:

Not set.



Description of corner evidence found:

Found painted line trees and 3" square post near surveyed point.

Corner falls near the Northeast corner of timbered area.

Description of monument and accessories | established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap marked: Set pipe 24" in the ground.

No rock in the area.

T4N R4OE
N1/16

S29 † S28

OR PLS 1051
1978

From which: A Tamarac 14" in dia. bears N85°E, 128.5 feet, scribed N1/16S28BT. A Tamarac 15" in dia. bears S65°W, 28.0 feet, scribed N1/16S29BT. Painted blazes red and 6" band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-2 and 54-4 on steel fence post 3' South and 54-2 and 54-9 on steel fence post 3' West of corner. Placed 54-5 on tree 5' West of corner.

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers
Dan T. Rowland

October 20, 1978

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of... County Surveyor..... County of... Union
State of... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the..20.. day of... November....., 1978.

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

**UNION COUNTY
SURVEYOR**

Date Received _____

Date Filed _____

By _____

File No. 73 - 83 R