


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. S-11

History of original corner establishment:

Corner was set in 1977 by P.L.S. 645 based on different corner position then that established in 1977 survey.



Description of corner evidence found:

Found 2 1/2" x 30" galvanized pipe set 25" in the ground and marked NC1/16S28.


Two trees were blazed and scribed as bearing trees.

The Northwest bearing tree is a Lodgepole Pine that has blown down after logging in the area.

Corner falls near the SE corner of timbered area.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point which is N41°21'E, 3.78 feet from 1977 brass cap, set 2 1/2" x 30" galvanized pipe with brass cap marked: Set pipe 24" in the ground.



No rock in the area.

From which: (Existing) A Lodgepole Pine 12" in dia. bears S37°E, 20.4 feet, scribed NC1/16S28XBT. (New) A Tamarac 12" in dia. bears N40°E, 62.8 feet scribed NC1/16S28BT. Placed 54-3 for my monument on existing BT and 54-4. Placed 54-3 and 54-4 on new BT. Placed brass washer stamped PLS 1051 on both foot blazes. Painted blazes red and 6" red band around on new BT. Existing BT painted red and yellow. Placed 54-2 and 54-4 on steel fence post 3' North and 54-2 and 54-9 on steel fence post 3' West of corner. Placed 54-5 on tree 10' North of corner. Location tags on road West and North of corner.

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Barry B. Barbour*

OREGON  
OCT. 17, 1975  
**BARRY B. BARBOUR**  
1051

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers  
Dan T. Rowland

October 25, 1978

Office of.....County Surveyor.....County of.....Union.....  
State of.....Oregon.....I hereby certify that the within instrument was filed in this office  
for record on the...20...day of...November.....1978

.....by.....  
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

<b>UNION COUNTY SURVEYOR</b>
Date Received <u>                    </u>
Date Filed <u>                    </u>
By <u>                    </u>
File No. <u>75-83R</u>

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

S-11

History of original corner establishment:

DIAGRAM  
Cap Stamped:  
N-C-1/16  
S 28  
1977  
ORLS 645

No previous history of this corner.

Description of corner evidence found:

No evidence found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a stamped 2 1/2" brass cap on a 30" galv. iron pipe buried in a mound of stone.

I set two bearing trees as follows:

A spruce 8" dia., which bears S 42 W, 28.5 feet, scribed N-C-1/16 S 28 BT.

A lodge pole pine 12" dia., which bears S 39 E, 19.9 feet, scribed N-C-1/16 S 28 BT.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*James H. Hambleton*  
12-20-77

OREGON  
JULY 10, 1954  
JAMES H. HAMBLETON  
645

Office of..... County of.....

State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by.....  
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY SURVEYOR  
Date Received \_\_\_\_\_  
Date Filed \_\_\_\_\_  
By \_\_\_\_\_  
File No. 81-83R