


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. T-3

History of original corner establishment:  
Not set.



Description of corner evidence found:  
None.

Corner falls in large area of Lodgepole Pines.

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap marked: Set pipe 24" in the ground.

T4N R40E  
C1/4 —+— S30  
OR PLS 1051  
1978

No rock in the area.

From which: A Lodgepole Pine 8" in dia. bears N06°E, 16.4 feet, scribed C1/4S30BT. A Lodgepole Pine, 10" in dia. bears S14°W, 14.8 feet, scribed C1/4S30BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-4 and 54-9 on steel fence post 3' South of corner. Placed 54-5 on tree 5' East of corner.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Barry B. Barbour*

OREGON  
OCT. 17, 1975  
BARRY B. BARBOUR  
1051

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers  
Dan T. Rowland

November 1, 1978

Office of... County Surveyor..... County of... Union.....  
State of... Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the... 20... day of... November....., 1978.

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY SURVEYOR**

---

Date Received 99-509

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 79-83R