


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. T-11

History of original corner establishment:

Not set.



Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap marked: Set pipe 8" in the ground to bedrock, and mound of stone around to cap.

T4N R40E
C1/4 + S28
OR PLS 1051
1978

From which: A Lodgepole Pine 21" in dia. bears S67°E, 56.2 feet, scribed C1/4S28BT. A Tamarac 12" in dia. bears S08°E, 53.7 feet, scribed C1/4S28BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-2 and 54-4 and 54-9 on steel fence post 3' West of corner. Placed 54-5 on tree 15' West of corner and 54-5 on main road 250' South of corner.

I hereby certify the above corner monument was reestablished as herein described.

Witnesses: David L. Landers
Dan T. Rowland

October 16, 1978

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour
OREGON
OCT. 17, 1978
BARRY B. BARBOUR
1051

Office of... County Surveyor..... County of... Union.....
State of... Oregon....., I hereby certify that the within instrument was filed in this office
for record on the... 20... day of... November....., 1978

(COUNTY OFFICIAL)

(DEPUTY)

SEARCHED INDEXED
SERIALIZED FILED
OCT 17 1978
FBI - PORTLAND

GPO 799-509

By _____

File No. 87-83R