

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Frank W. Campbell under G.L.O. contract number 507 dated June 28, 1884.

Surveyor General's records state:

Set a fir post 3 ins square 3 ft long 2 1/4 ins in the ground for 1/4 sec cor marked 1/4 S on west face from which

A fir 25" dia bears N 20° W., 13 lks dist marked 1/4 S BT
A fir 8" dia bears S 47° E., 43 lks dist marked 1/4 S BT

Description of corner evidence found:

NONE

Description of monument and accessories established to perpetuate the original location of this corner



Set a 2 1/2" brass cap on a 2" iron pipe 31" long 6" above the ground with a 6' steel fence post alongside with sign 54-4 attached.

New bearing trees:

A fir 8" dia bears N 20° W., 6.0 ft dist marked 1/4 S 26 BT
A larch 7" dia bears S 53° E., 14.5 ft dist marked 1/4 S 25 BT

Each BT has a sign 54-3 attached 6" below a band of red paint and has a brass washer marked RPE 2808 nailed flush with BT blaze.

Brass cap is marked: T 4 N R 40 E
 1/4
 |
 S 26 S 25
 |
 R P E 2 8 0 8
 1976



Office of Surveyor County of Union
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 26 day of August
..... by
(COUNTY OFFICIAL) (DEPUTY)

UNION COUNTY REGISTER
Date Received _____
Date Filed _____
By _____
File No. <u>94-83R</u>
<small>GPO 796-333</small>