


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. U-6

History of original corner establishment:
Not set.



Description of corner evidence found:
None.

Corner is about 200' South of main road near corner of clear cut.

Description of monument and accessories | established to perpetuate the original location of this corner:

T4N R40E
SW1/16 + S29
OR PLS 1051
1978

At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap marked: Set pipe 25" in the ground.

No rock in the area.

From which: A Fir 22" in dia. bears N67°E, 26.5 feet, scribed SW1/16S29BT. A Fir 18" in dia. bears S05°W, 15.5 feet, scribed SW1/16S29BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-2 and 54-4 on steel fence post 5' North and 54-2 and 54-9 on steel fence post 5' East of corner. Placed 54-5 on tree 25' North of corner.

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers
Dan T. Rowland

October 24, 1978

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of...County Surveyor..... County of...Union.....
State of...Oregon..... I hereby certify that the within instrument was filed in this office
for record on the...20... day of...November....., 1978

(COUNTY OFFICIAL)

(DEPUTY)

Form R6-7100-57 (9/71)

UNION COUNTY SURVEYOR	
Date Received _____	GPO 799-509
Date Filed _____	
By _____	
File No. <u>97-83R</u>	