


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. U-7

History of original corner establishment:
Not set.




Description of corner evidence found:
None.

Corner falls near the S.E. corner of clear cut.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap marked: Set pipe 25" in the ground.



No rock in the area.

From which: A Fir 18' in dia. bears N62°E, 54.6 feet, scribed SC1/16S29BT. A Fir 15" in dia. bears S63°W, 90.6 feet, scribed SC1/16S29BT. Painted blazes red and 6" red band around. Placed 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051 on foot blazes. Placed 54-2 and 54-4 on steel fence post 5' South and 54-2 and 54-9 on steel fence post 4' West of corner. Placed 54-5 on large tree 25' East of corner.

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers
Dan T. Rowland

October 31, 1978

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of County Surveyor County of Union
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 20 day of November, 1978

..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 99.509

Date Filed _____

By _____

File No. 98-83R