CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:	Y- /
	DIAGRAM
Corner established in 1884 by Frank W. Campbell, under General Land Office Contract No. 507.	T4N R4OE
Surveyor General Records State: Set a post (pine) 4" square,4 ft. long 24" in ground for corner to Sections 28-29-32 &33 marked: T4N S.28 in NE;R40E S.33 in SE; S.32 in SW and S.29 in NW faces with 1 notch on S. and 4 notches on E edges from which	S.32 S.33
A tamarack, 8" diam bears N.30°E 9 links dist. mk A spruce 4" diam. bears S.40°E. 4 links dist. mkd A tamarack, 8" diam. bears S.47°W 5 links dist. mk A spruce, 10" diam. bears N.50°W. 4 links dist. mk	:T4N R40E S.33 BT
Description of corner evidence found:	
At assumed location I found the rotted end of the or from which:	iginal post,
A tamarack, now 8" snag of ground, scribing visible,	bears S.47°W.
5 links (3.3') dist.	
A spruce, found 4' section on ground, tree cut down 4 links (2.64') dist. (portion of scribing visible	, bears N.50 W.
A fir. 6" Diam. bears S.43"W. 28.2 feet dist.	T4N R40E S.29 S.28 S.32 S.33 ORLS 506 1973 BTs.
REGISTERED PROFESSIONAL LAND SURVEYOR	SURVEYOR
	to Received
Wohl a Phones	
OREGON	te Filed
MAY 13, 1960 RALPH P. THOMPSON 506 By	
Office of county surveyor County of Union Fil	a.No. <u>1.03 - 83R</u>
State of Oregon , I hereby certify that the within instrument was filed in a for referd on the 2.7 pdpy pf	his office
(COUNTY OFFICIAL)	n., (signed)