


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. V-12

History of original corner establishment:

Not set.



Description of corner evidence found:

None.

Corner is 30' Southeast of a track road.

Description of monument and accessories established to perpetuate the

original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap marked: Set pipe 24" in the ground and mound of stone around to cap.

T4N R40E  
 S28  
 E1/16  $\frac{+}{S33}$   
 OR PLS 1051

From which: A Tamarac 15" in dia. bears N02°E, 53.2 feet, scribed  
 E1/16S28BT. A Tamarac 18" in dia. bears S37°E, 34.7 feet, scribed  
 E1/16S33BT. Painted blazes red and 6" red band around. Placed  
 54-3s and 54-4s on BTs. Placed brass washer stamped PLS 1051  
 on foot blazes. Placed 54-2 and 54-4 on steel fence post 5' East  
 and 54-2 and 54-9 on steel fence post 5' North of corner. Placed  
 54-5 on a tree 15' South and 75' West on tree at road.

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: David L. Landers  
Dan T. Rowland

October 16, 1978

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR

*Barry B. Barbour*

OREGON  
 OCT. 17, 1975  
 BARRY B. BARBOUR  
 1051

Office of..... County Surveyor..... County of..... Union.....  
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office  
 for record on the...20... day of...November....., 19...78

..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_  
 Date Filed \_\_\_\_\_  
 By \_\_\_\_\_  
 File No. 105-83R