


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. X-18

History of original corner establishment:

None .



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" x 30" galvanized pipe and brass cap marked: Set pipe 6" below the road surface. Surveyed point falls on right side of main Forest Service Road.
 From which by magnetic declination of N20°E:
 A 18" fir bears S05°E., 83.5 ft. scribed CWL/16S35 BT.
 A 18" fir bears N48°W., 37.9 ft. scribed CWL/16S35 BT.
 Painted blazes red and 6" red band around. Placed 54-3s, 54-9s and brass washers stamped PLS 1051 on BTs. Placed 54-2 on a steel fence post 27.5 ft. north and 54-2 and 54-9 on a steel fence post 30.3 ft. west of the corner.

T4N R40E
W 1/16

C —+— C

S35
OR PLS 1051
1981

I hereby certify that the above corner monument was established as herein described.

Witnesses: Daniel Rowland
Troy Phillips

July 31, 1981

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of.....County Surveyor..... County of.....Union.....
 State of.....Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the 29 day of.....August....., 1981
HOWARD L. FERRY..... by Ray J. Langlit
 (COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 7.28.81

Date Filed _____

By _____

File No. 112-83R