


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. ^A X-19

History of original corner establishment:

Corner was originally established under G. L. O. contract No. 507 by Frank W. Campbell on August 8, 1981. Surveyors General's notes state: "Set a fir post 3 ft. long 3 ins. square 18 ins. in the ground for 1/4 Sec corner marked 1/4S on N. face from which: A fir 10 ins. diam. bears S9°W., 24 lks. dist. marked 1/4S BT. A fir 6 ins. diam. bears N41°W., 24 lks. dist. marked 1/4S BT."



Description of corner evidence found:

Found 24" Fir stump. Opened old grown over blaze and found scribed BT. Measured N09°E., 15.7 ft. and found rotten tamarac post going 24" in the ground. No trace of NW BT.

Description of monument and accessories I established to perpetuate the original location of this corner:

At the above point set 2 1/2" x 30" galvanized pipe and brass cap marked: Set pipe 26" in the ground. No rock in the area.
From which by magnetic declination of N20°E:
A 15" Fir bears N55°E., 41.7 ft. scribed 1/4S35 BT.
A 14" Fir bears S27°W., 50.8 ft. scribed 1/4 S2 BT.
Painted blazes red and 6" red band around.
Placed 54-3s, 54-4s and brass washers stamped PLS 1051 on BTs.
Placed 54-4 on steel fence post 5' east of the corner.

T4N R40E
S35
1/4 ———
S2
T3N
OR PLS 1051
1981

I hereby certify that the above corner monument was reestablished as herein described.

Witnesses: Daniel Rowland
Beverly Weaselhead

June 24, 1981

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Barry B. Barbour

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1051

Office of.....County Surveyor..... County of...Union...and...Wallowa.....
Oregon
State of....., I hereby certify that the within instrument was filed in this office
for record on the 24 day of.....August....., 1981.
HOWARD L. PERRY..... by Gay L. Langlit
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**
Date Received _____
★ GPO—788-278
Date Filed _____
By _____
File No. 182-832