


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. C-21

History of original corner establishment:

In 1882, under Contract No. 451, Rufus S. Moore set a post, from which a 4" Pine bears N60°W, 8 lks., and a 4" Pine bears S40°E, 22 lks.



Description of corner evidence found:

No corner evidence found.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2 1/2"x30" aluminum capped aluminum pipe rising 5", stamped:

New BT's:

- A 9" Fir bears N60 1/2°W, 119.7 ft., scribed 1/4 S2 BT.
- A 7" W. Larch bears N30°E, 130.5 ft., scribed 1/4 S1 BT.

T4S R33 1/2E
1/4
S2 | S1
RLS 1848
1984

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Set metal fence post 4 ft. north of corner.

Declination: 19 1/2°E

Witness: D. Scott

From 2110-670, northeasterly on 2110-710 .2 mi. Corner is 350 ft. east of the road.

I hereby certify the above described corner monument and/or accessories was established as described, on May 8, 1984.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

OREGON
JULY 13, 1879
B. A. SUTTON
1848

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office
for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 7-2-84
Date Filed 7-3-84
By G. LANGLITZ, DEPUTY
File No. 919-84R