


LAND CORNER RECORD

1. T 4S R 33 1/2 E No. N23 Cor. 1/4 Mer. Will State Oregon (Rectangular) N. F. Wallowa Whitman Dist. LaGrande

2. Corner Status



1/4 corner

7. Photo Identification

Photo No. UBM-3-6
Ident. By: S. Kelly J. Wick
11-10-65

8. Plane Coordinate Position Data

State _____ Zone _____
X _____
Y _____
Estab. By _____
Field Book No. _____
Where Filed _____

9. Evaluation

Authentic _____
Needs Verif. _____ Monument _____
Re-estab. _____ Survey _____
Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: Rock monument. 3" x 12" x 15"
Ground level - good condition. No markings.

5. Investigation Notes: None found. A live 22" PP 44' west
of rock has location poster indicating corner.

6. Signed S. Kelly Title Forester Date 11-10-65

UNION COUNTY SURVEYOR

Date Received _____

Date Filed 12-21-87

By G. LANGLITZ, DEPUTY

File No. 286-87R

N-23