


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1881, under Glo Contract No. 410, George S. Pershin set a stone 18x12x6, from which a 9" Pine bears N67°W, 60 lks.; an 8" Pine bears N70°E, 21 lks.; an 8" Pine bears S36°E, 39 lks.; and a 7" Pine bears S47°W, 30 lks.

Index File No. <sup>A</sup> 8-21



Description of corner evidence found:

Found stone 16"x9"x7" firmly set with 5 notches on SE corner, 1 notch on NW corner.

No bearing trees found. Root hole with dead & down & rotted tree S36°E, 25.7 ft., no scribing.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2 1/2"x31" aluminum pipe with 3 1/4" aluminum cap rising 4", stamped:

New BT's:

- A 5.0" L. Pine bears N35°W, 17.0 ft., scribed T3S R33E S35 BT.
- A 5.1" L. Pine bears N60°E, 28.8 ft., scribed T3S R33E S36 BT.
- A 5.2" L. Pine bears S40°W, 9.7 ft., scribed T4S, R33E S2 BT.
- A 6.0" L. Pine bears S55°E, 13.1 ft., scribed T4S R33E S1 BT.

		T3S
R		
33	S35   S36	
E	S2   S1	
	1983	
	LS 1848	
	T4S	

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Set metal fence post 4 ft. north of corner.


Compass Declination: 19 1/2°E

Witness: N. Petz

From 2110 northeasterly 1.5 mi. to posted south line, S 36, Corner is west 220 ft. downhill in lodgepole thicket.

I hereby certify the above described corner monument and/or accessories was established as described on September 13, 1983.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR



OREGON  
JULY 13, 1979  
B. A. SUTTON  
1 8 4 8

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

**UNION COUNTY  
SURVEYOR**

---

Date Received 7-2-84

Date Filed 7-3-84

By G. LANGLITZ, DEPUTY

File No. 883-84 R