


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1881, under GLO Contract 410, George S. Pershin set a post, from which an 8" Tamarack bears N46°W, 33 lks. and a 7" Fir bears S38°W, 9 lks.

Index File No. ^A 7-23



Description of corner evidence found:

No corner monument found.

Bearing trees found:

- A 20" Fir bears S36°W, 5.9 ft., damaged.
- A 16" W. Larch stump bears N42°W, 21.8 ft., scribing visible "BT".

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2 1/2"x30" aluminum capped aluminum pipe rising 7", stamped:

New BT's:

- An 8.5" W. Larch bears N27°E, 25.7 ft., scribed 1/4 S36 BT.
- A 13.5" W. Larch bears S62 3/4°E, 17.2 ft., scribed 1/4 S1 BT.

T3S R33E
S36
1/4 S 1
1983
RLS 1848
T4S

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982.

Set metal fence post 4 ft. north of corner.

Compass Declination: 19 1/2°E

Witness: N. Petz

From the posted line where it crosses 2110-320, follow the posted line east 1/2 mi. to corner.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

B. A. Sutton

OREGON
JULY 13, 1979
B. A. SUTTON
1 8 4 8

I hereby certify the above described corner monument and/or accessories was established as as described on October 18, 1983

Office of..... County of.....
 State of....., I hereby certify that the within instrument was filed in this office
 for record on the..... day of....., 19.....

(COUNTY OFFICIAL)

(DEPUTY)

**UNION COUNTY
SURVEYOR**

Date Received 7-2-84

Date Filed ^{GPO} 7-3-84

By G. LANGLITZ, DEPUTY

File No. 884-84 R