

USDA-FOREST SERVICE

Index

File No. L 21

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

Tract or

Survey No. _____

Cor.

No. _____

T 4S R. 33E


R.D. LaGrande

County Umatilla

Merid. Willamette

N.F. Wallows-Whitman State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Mound of stones, no visible marks.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Section 14- 18" DF live in good condition, scribe grown over, good blaze marks.

Section 13- 10" DF live in good condition, scribe grown over, good blaze marks.

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

PHOTO IDENTIFICATION DATA

Photo No. 777-119

Filed At. LaGrande

Object Ident. Approx corner

Ident. By _____

Signature

PLANE COORDINATE POSITION DATA

State _____ Zone _____

X _____

Y _____

Estab. By _____

Agency

Signature David R. Dahlstrom

Title CET

Division _____

Headquarters LaGrande

Date 6-15-83

7100-52 (3. 68)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed 12-21-87

By G. LANGLITZ, DEPUTY

File No. 281-87R

L-21