


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not previously set.



Description of corner evidence found:

Not previously set.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2" x 30" galvanized iron pipe with 2 1/2" brass cap marked: Pipe is set in ground 24" with a collar of stone. A steel fence post is set 5' from the brass cap with a USFS Land Survey Monument sign attached.



Bearing Trees:

A 9" Ponderosa Pine bears S44°00'E, 66.6' scribed W 1/16 S1 BT in a single blaze. A 13" Ponderosa Pine bears S61°45'W, 74.7' scribed W 1/16 S1 BT in a single blaze. A 3/4" aluminum washer stamped RLS 852 is nailed between the letters B and T on each tree. A 6" red band is painted around each tree and USFS Bearing Tree and Land Survey Monument signs are attached.

I certify the above corner point was established as hereon described on August 21, 1986.

SEE SURVEY
35-86

UNION COUNTY SURVEYOR

Date Received 10-2-86


Date Filed 10-13-86

By G. LANGRIZ DEPUTY

File No. 175-86 R



David L. Haddock



Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)