


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not previously set.



Description of corner evidence found:

Not previously set.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2" x 30" galvanized iron pipe with 2 1/2" brass cap marked: Pipe is set 18" into the ground with a collar of stone. A steel fence post is set 5' from the brass cap with a USFS Land Survey Monument sign attached.



Bearing Trees:

A 13" Douglas Fir bears S51°45'W, 26.3' scribed CN 1/16 S2 BT in a single blaze. A 14" Douglas Fir bears N34°15'W, 30.3' scribed CN 1/16 S2 BT in a single blaze. A 3/4" aluminum washer stamped RLS 852 is nailed between the letters B and T on each tree. A 6" red band is painted around each tree and USFS Bearing Tree and Land Survey Monument signs attached.

I certify the above corner point was established as hereon described on September 2, 1986.

SEE SURVEY  
35-86

**UNION COUNTY SURVEYOR**

---

Date Received 10-2-86

Date Filed 10-13-86

By G. LANGLITZ DEPUTY

File No. 172-86 R

**REGISTERED PROFESSIONAL LAND SURVEYOR**

*David L. Haddock*

**OREGON**  
JULY 12, 1968  
**DAVID L. HADDOCK**  
852

Office of..... County of.....  
 State of....., I hereby certify that the within instrument was filed in this office  
 for record on the..... day of....., 19.....  
 ..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)