


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Not previously set.



Description of corner evidence found:
Not previously set.

UNION COUNTY SURVEYOR

Date Received 10-2-86

Date Filed 10-13-86


By G. LANGLITZ DEPUTY

File No. 171-86 R

SEE SURVEY 35-86

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2" x 30" galvanized iron pipe with 2 1/2" brass cap marked: Pipe is set into ground 14" in a mound of stone. A steel fence post is set 5' from the brass cap with a USFS Land Survey Monument sign attached.



Bearing Trees:

An 11" Ponderosa Pine bears N49°15'W, 128.6' scribed N 1/16 S2 BT in a single blaze. An 8" Ponderosa Pine bears N73°30'E, 82.5' scribed N 1/16 S1 BT in a single blaze. A 3/4" aluminum washer stamped RLS 852 is nailed between the letters B and T on each tree. A 6" red band is painted around each tree and USFS Land Survey Monument and Bearing Tree signs attached.

I certify the above corner point was established as hereon described on August 27, 1986.

REGISTERED PROFESSIONAL LAND SURVEYOR

David L. Haddock

OREGON
JULY 12, 1969
DAVID L. HADDOCK
852

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)