


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

In 1882, under GLO Contract No. 451, Rufus S. Moore set a stone 14x7x7 in mound, with no bearing trees.

Index File No. C-25



Description of corner evidence found:

Found original stone with faint "1/4" on north side.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set 2 1/2"x30" aluminum capped aluminum pipe rising 20" in mound, stamped: Set original stone in mound on north side.

New BT's:

A 6.5" x 5.5" double P. Pine bears N7 1/2°E 288.0 ft., 6.5" part scribed 1/4 S6 BT.  
An 8.5" P. Pine bears S84 1/2°W, 115.4 ft., scribed 1/4 S1 BT.

T4S		
R33	1/2E	1/4 R34E
S1		S6
1984		
RLS 1848		

Painted blazes and attached signs as per Standard Specifications for Cadastral Surveys, USFS Region 6, March 1982. Set metal fence post 4 ft. north of corner.

Declination: 19 1/2°E  
Witness: D. Scott

From 2100-146, south on 21 1,000 ft. Corner is in large open area 300 ft. west of the road.

I hereby certify the above described corner monument and/or accessories was established as described on May 11, 1984.

<b>REGISTERED PROFESSIONAL LAND SURVEYOR</b>
<i>B. Sutton</i>
OREGON JULY 13, 1979 B. A. SUTTON 1848

Office of..... County of.....  
 State of....., I hereby certify that the within instrument was filed in this office  
 for record on the..... day of....., 19.....  
 ..... by .....  
 (COUNTY OFFICIAL) (DEPUTY)

<b>UNION COUNTY SURVEYOR</b>	
Date Received	<u>7-2-84</u>
Date Filed	<u>7-3-84</u>
By	<u>G. LANGLITZ, DEPUTY</u>
File No.	<u>920-84 R</u>