


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not previously set.




Description of corner evidence found:

Not previously set.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2" x 30" galvanized iron pipe with 2 1/2" brass cap marked: Pipe is set into ground 8" in a mound of stone. A steel fence post is set 5' from the brass cap with a USFS Land Survey Monument sign attached.



Bearing Trees:

A 22" Ponderosa Pine bears N10°15'W, 192.0' scribed SW 1/16 S1 BT in a single blaze. A 12" Ponderosa Pine bears N89°45'W, 113.4' scribed SW 1/16 S1 BT in a single blaze. A 3/4" aluminum washer stamped RLS 852 is nailed between the letters B and T on each tree. A 6" red band is painted around each tree and USFS Bearing Tree and Land Survey Monument signs attached.

I certify the above corner point was established as hereon described on September 4, 1986.

SEE SURVEY
35-86

UNION COUNTY SURVEYOR

Date Received 10-2-86

Date Filed 10-13-86

By G. L. LANGLIZ, DEPUTY

File No. 163-86 R

REGISTERED PROFESSIONAL LAND SURVEYOR

David L. Haddock

OREGON
JULY 12, 1988
DAVID L. HADDOCK
852

Office of..... County of.....
State of..... I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)