


LAND CORNER RECORD
(Rectangular)

1. T 4S R 33 1/2E No. P-25 Cor. 1/4 Mer Will State Oregon N. F. Wallowa Whitman Dist. LaGrande

2. Corner Status



3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: Rock 8x12x9 Ground level
Poor condition. 4 rocks assumed to be the 1/4 cor.

5. Investigation Notes:

1 BT-20" PP approx. 90' S60°W from corner.
Location poster on this one.

1 possible BT 34" Dead PP Snag. approx. 143'
E. of corner.

I painted the corner and BT's red. The
cor. is in an opening - 25' W. of corner is a
very small draw. The cor. is approx 843' N
of Salisbury Road.

7. Photo Identification

Photo No. NBM-0-4-3
Ident. By: S. Kelly 11-10-65

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

6. Signed S. Kelly Title Forester Date 11-10-65

UNION COUNTY SURVEYOR

Date Received _____

Date Filed 12-21-87

By G. LANGLITZ, DEPUTY

File No. 287-87R

P-1