


LAND CORNER RECORD

1. T4S R33 1/2 E No. R25 Cor. Sec. Mer Will State Oregon (Rectangular) N. F. Wallowa Whitman Dist. La Grande

2. Corner Status

R-25



7. Photo Identification

Photo No. _____

Ident. By: _____

8. Plane Coordinate Position Data

State _____ Zone _____

X _____

Y _____

Estab. By _____

Field Book No. _____

Where Filed _____

9. Evaluation

Authentic _____

Needs Verif. _____ Monument _____

Re-estab. _____ Survey _____

Land Status _____

3. Original Description _____ Vol. _____ Page _____ Where Recorded _____

4. Description of Corners: Rock Pile 10-12"
Grnd. level - good condition.

5. Investigation Notes:

1 BT found 20" Dead PP. Is a blowdown and is badly decayed. Approx. 66' from cor. at a bearing of 208° from corner. S28°W No Declination.

Corner is in a large opening. Approx. 12' S of cor is a 5" PP sapling with location poster on it. The cor. is Approx 1797' South of Salisbury road on way to fire road No 17 H. Corner has been painted red.

6. Signed S. Kelly J. Wick Title For. & D.R Date 11-10-65

UNION COUNTY SURVEYOR

Date Received _____

Date Filed 12-21-87

By G. LANGLITZ, DEPUTY

File No. 288-87R

R-1