

MONUMENT : DESCRIBE

ACCESSORIES : DESCR

Work Done By

Certified Cor. Record Pr.

Index File No.

Form 874-9 - Revised November 1939

U. S. Department of Agriculture  
FOREST SERVICE

R21

M

Wallace - Vietnam NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 43 R. 34E Wm Mer.

Corner common to Sections 23, 24, 25, and 26

Corner consists of a Rock (not) in place  
State condition

Dimensions above ground 10 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

BT BT BT BT

Species Pine Pine Pine Pine

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? ...

If not, why?

*E. Johnson*  
(Signature)

(Date)

(Title)

16-12765-1

**UNION COUNTY SURVEYOR**

---

Date Received \_\_\_\_\_

Date Filed 12-21-87

By G. LANGLITZ, DEPUTY

File No. 297-87R

R-21