

OREGON CORNER RESTORATION FORM

Section: 2  
Township: 4S  
Range: 35 EWM  
County: UNION  
Date: 03/10/98  
Corner Designation: A-20

Previous Renewals/Surveys, etc.: None

Monument(s) & Accessories Found (Condition & Source): None.

Monument Detail: TOMKINS SURVEYING  
T3S  
R35E  
S35  
E 1/16 +  
S2  
1998  
T4S R35E  
WA25893 OR2360 OR2820

Monument Set (Procedures & Description):

At the surveyed position of the East 1/16 on the North line of Section 2 I set a 5/8" x 30" rebar with a 1 1/2" aluminum cap, marked as shown, 29" in the ground, surrounded with a mound of earth.

New Accessories:

A steel fence post with a land survey monument sign was placed alongside. A 5/8" x 30" rebar with a yellow plastic cap stamped "Tomkins Surveying" and a brass washer stamped "WA19619 OPLS02820" attached, bears N33°59'W 101.25'.

An 18" ponderosa pine bears S02°33'E 83.8', marked E 1/16 S2 BT. The Monumented S.W. corner of Section 36, Township 3 South, Range 35 East, W.M. bears S89°40'10"E 275.52 feet.

Location & Comments:

The corner is in an open field 88' South of an East-West fence line and 36' West of a North-South fence line.

Compass Declination:

19° East

Surveyor's Seal

Firm/Agency: Tomkins Land Surveying, Inc.  
20 E. Poplar, Suite 204  
Walla Walla WA 99362

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Greg E. Flowers*

OREGON  
JUNE 30, 1997  
GREG E. FLOWERS  
02820LS

Party Chief: Greg E. Flowers

Notes: Greg E. Flowers

Witness: Brianna Slater

RENEWS 12/31/99  
5/14/98

6/22/98  
8/29/98  
R. ROBINSON, DEPUTY  
047-1998R