OREGON CORNER RESTORATION FORM

Section:

2

Township: 45

Range:

35 EWM

County:

UNION

Date:

03/10/98

Corner Designation: C-20

Previous Renewals/Surveys, etc.: None

Monument(s) & Accessories Found (Condition & Source): None.

Monument Detail: TOMKINS SURVEYING

T4S R35E

C-E 1/16 + S2

1998

WA25893 OR2360 OR2820

Monument Set (Procedures & Description):

At the location determined by survey set a 5/8" x 30" rebar 30" in the ground, with a 12" aluminum cap stamped as shown attached.

New Accessories:

A steel fence post with a land survey monument sign attached was placed along side.

A 5/8" x 30" rebar with a yellow plastic cap stamped "Tomkins Surveying" set at the Southwest corner of parcel 2 of Union County Partition plat No. 1994-28 bears S89°15'52"E 247.39 feet.

Location & Comments:

The corner is located in a North-South fence line, 100' East of the Grande Ronde River Road.

Compass Declination:

19° East

Firm/Agency:

Tomkins Land Surveying, Inc.

20 E. Poplar, Suite 204 Walla Walla WA 99362

Party Chief:

Greg E. Flowers

Notes:

Greg E. Flowers

Witness:

Brianna Slater

Surveyor's Seal

OREGON JUNE 30, 1997 GREG E. FLOWERS 02820LS

RENEWS 12 131 199

5/14/18

Day 12 and 6/27/98 - 8/29/98 R ROBINSON DEPUTY De 10 048-1998R