

OREGON CORNER RESTORATION FORM

Section: 2
Township: 4S
Range: 35 EWM
County: UNION
Date: 03/10/98
Corner Designation: D-20

Previous Renewals/Surveys, etc.: None

Monument(s) & Accessories Found (Condition & Source): None.

Monument Detail: TOMKINS SURVEYING
T4S R35E
S-E 1/16 + S2
1998
WA25893 OR2360 OR2820

Monument Set (Procedures & Description):

At the location determined by survey set a 5/8" x 30" rebar 12" in the ground to refusal and surrounded with a mound of stone, with a 1 1/2" aluminum cap stamped as shown attached.

New Accessories:

A steel fence post with a land survey monument sign attached was placed along side.

A 12" Douglas fir bears N78°16'E 8.1 feet, marked SE 1/16 S2 BT.

A 10" Douglas fir bears S27°12'E 13.5 feet, marked SE 1/16 S2 BT.

Location & Comments:

The corner is located on the point of a rocky ridge just above a basalt outcropping 40' South of an East-West fence. And 100' East of the Grande Ronde River Road.

Compass Declination:

19° East


Firm/Agency: Tomkins Land Surveying, Inc.
20 E. Poplar, Suite 204
Walla Walla WA 99362

Party Chief: Greg E. Flowers


Notes: Greg E. Flowers

Witness: Brianna Slater

Surveyor's Seal



Greg E. Flowers



RENEWS 12/31/99

5/14/98

6/22/98
8/29/98
R. ROBINSON, DEPUTY
049-1998R