## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner has not been previously set. DI AGRAM

T45 R35E

N1/16 5 7 5 8

1989 FLS 699

Description of corner evidence found: Corner is being set by this survey.

> UNION COUNTY SURVEYOR
>
> Date Received 9-25-89
>
> Date Filed 9-25-89
>
> By G.LANGLITZ
>
> File No. 176-89 R

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 24" aluminum cap, marked as shown in the diagram, 18" in the ground to solid rock, at a point as determined by the procedures set forth in the MANUAL OF INSTRUCTIONS FOR THE SURVEY OF PUBLIC LANDS for the subdivision of sections. Built a mound of rock to be 36" in diameter by 12" high around the monument, from which new BTs are:

9° Ponderosa pine bears \$78°M, 58.0 feet scribed N1/16 \$7 BT

Attached BT and Land Survey Monument signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between the SE and S4 corners of Section 7 as shown on MOS 43-76, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground. Set steel fence posts 5 feet E and 5 feet W of the corner on the National Forest boundary lines. Attached Forest Boundary signs to each post and a Land Survey Monument sign to the E post.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on July 19, 1989, I established the corner as herein described.

THE

PROFESSIONAL LAND SURVEYOR

REGISTERED

OREGÓN JULY 9, 1965 LELAND LEE MYERS 699

Union County Surveyor

USDA-FS Contract No. 04M3-8-6103 T4S R35E F-5