

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Index: F9

North 1/16 Corner Sections 8 and 9, T.4S., R.35E., W.M

This township was subdivided by Moore in 1884.
He did not set the 1/16 corners at that time.

1	DIAGRAM	1
1	ORLS 852	1
1	1	1
1	N ---	1
1	16	1
1	S8 S9	1
1	+	1
1	T4S R35E	1
1	WALS 13922	1
1		1

Description of corner evidence found:
None

Description of monument and accessories I established to perpetuate the original location of this corner:

In the position for the North 1/16 corner, proportioned between the found section corners at the north and south ends of the line between Sections 8 and 9, I set a 5/8" x 30" rebar with 2" diameter aluminum cap stamped as shown in the diagram above.

From which, I marked the following witness trees:

A 28" dbh Ponderosa Pine bears S33°45'E, 2.3', scribed N1/16 S9 BT.

A 27" dbh Ponderosa Pine bears S66°45'W, 42.6', scribed N1/16 S8 BT.

An aluminum washer stamped RLS 852 is nailed between the letters B and T on each new tree. All the BT's have BT signs attached.

This work was done June 22, 1993.

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

David L. Haddock

**OREGON
JULY 12, 1988
DAVID L. HADDOCK
852**

Office of _____ County of _____
State of _____, I hereby certify that the within instrument was filed
in this office for record on the _____ day of _____, 19____.

(COUNTY OFFICIAL)

(DEPUTY)

UNION COUNTY SURVEYOR	
Date Received	<u>9/1/93</u>
Date Filed	<u>9/10/93</u>
By	<u>[Signature]</u>
File No.	<u>044-1393C</u>