CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner has not been previously set. DI AGRAH

T45 R35E

C1/4+5 B

1989 PLS 699

Description of corner evidence found: Corner is being set by this survey.

SURVEYOR

Date Received 9-25-89

Date Filed 9-25-89

& G.LANGLITZ

File No. 179-89 R

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 2%" aluminum cap, marked as shown in the diagram, 22" in the ground to solid rock, at a point as determined by the procedures set forth in the MANUAL OF INSTRUCTIONS FOR THE SURVEY OF PUBLIC LANDS for the subdivision of sections. Built a mound of rock & earth to be 36" in diameter by 8" high around the monument, from which new BTs are:

14" Ponderosa pine bears N31° 15'N, 34.5 feet scribed C1/4 S8 BT

Attached BT and Land Survey Monument signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between the SE and S% corners of Section 7 as shown on MOS 43-76, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground. Set steel fence posts 5 feet N and 5 feet S of the corner on the National Forest boundary lines. Attached Forest Boundary signs to each post and a Land Survey Monument sign to the N post.

I, Leland I. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on July 18, 1989, I established the corner as herein described.

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGON LELAND LEE MYERS

FILED

IN THE OFFICE OF THE Union COUNTY SURVEYOR

THIS _____ DAY OF _______, 19_____

Union County Surveyor