CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

History of original corner establishment:	Index:	610
Center west 1/16 Corner Section 9, T.4S., R.35E., W.M.	Jackson on supplementation with stress elementation	enne amandalahan pergangangan anggangan in
This township was subdivided by Moore in 1884. He did not set the 1/16 corners at that time.	1 CW 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1
Description of grane midden of found		
Description of corner evidence found: None		
	The control of the co	
Description of monument and accessories I established original location of this corner: In the position for the North 1/16 corner, determined Manual instructions and the original locations of the east quarter corners and the northwest and southwest section 9, I set a 5/8" x 30" rebar with 2" diameter a stamped as shown in the diagram above. From which, I set the following reference monuments: A 1/2" x 24" rebar with 2" diameter aluminum cap under fence line, bears N22°15'W, 66.2' marked T4S R35E CW+1/16 A 1/2" x 24" rebar with 2" diameter aluminum cap drive outcrop, bears S6°45'W, 37.3' marked T4S R35E CW+1/16 REGISTERED PROFESSIONAL LAND SURVEYOR	as per 19 north, so crners of luminum of an east /16 S9 Pl	973 BLM buth and f ap west S 852.
Office ofCounty of State of, I hereby certify that the within i	nstrument	: was filed
this office for record on the day of		_, 19
(COUNTY OFFICIAL) (DEPUTY	* 1 T	
「ANO ME TO LINE OF THE LINE OF THE METERS	Maria Ma	ensing homeomethologically, or the three t

UNION COUNTY SURVEYOR
Date Received 9/1/93
Data Filod 9/10/93
Expertistion
File No. 0 42-1993 R