

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

DIAGRAM

Corner was established by Rufus S. Moore, US Deputy Surveyor, during the original survey Contract No. 451 dated June, 1882.

T4S R35E

Set a basalt stone 18x12x4 12 ins in ground for ¼ sec cor marked 1/4 on N face, and raised a mound of stone alongside. Pits impractical

1/4 $\frac{S\ 7}{S18}$

Corner was monumented by Duane Griffith, PLS 644, during a retracement survey dated July, 1976. (I did not find a record of what was found at the corner.)

1976
PLS 644

Set 1" galv pipe with 2½" brass cap, marked as shown in the diagram.

Description of corner evidence found:

Found a 1" galv pipe with 2½" brass cap standing 16" out of the ground surrounded by a rock mound.

No bearing trees were previously established.

Description of monument and accessories I established to perpetuate the original location of this corner:

Maintained the corner by improving the rock mound around the monument to be 34" in diameter and 12" high and set two rebar bearing objects to perpetuate the corner monument. I do not certify the correctness of this monument by doing this maintenance work.

No new bearing trees set because no trees are available.

No. 4 rebar bears S86° 30'E, 23.5 feet with a yellow plastic cap marked PLS 699

No. 5 rebar bears N1° 30'W, 15.8 feet with a yellow plastic cap marked PLS 699

Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between the SE and SW corners of Section 7 as shown on MOS 43-76.

Set steel fence posts 5 feet N and 5 feet S of the corner on the National Forest boundary lines. Attached Forest Boundary signs to each post and a Land Survey Monument sign to the N post.

| |
|------------------------------|
| UNION COUNTY SURVEYOR |
| Date Received <u>9-25-89</u> |
| Date Filed <u>9-25-89</u> |
| By <u>G. LANGUITZ</u> |
| File No. <u>182-89R</u> |

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on July 23, 1989, I maintained the corner as herein described.

REGISTERED PROFESSIONAL LAND SURVEYOR



OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Union COUNTY SURVEYOR

THIS ____ DAY OF _____, 19__

Union County Surveyor

UNION COUNTY
SURVEYOR

T4S35J03

Date Received 3/8/13

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 4 S., R. 35 E., Willamette Meridian, Oregon

Date Filed 3/8/13

By ML DEPUTY

~~From this point, Angle Point No. 6 on the westerly right-of-way of Oregon State Highway No. 244, bears N. 24° 09' 01" E., 4.41 ft. dist. Hereinafter described.~~

File No. 204-2013R

~~From this same point, Angle Point No. 8 on the westerly right-of-way of Oregon State Highway No. 244, bears S. 24° 09' 01" W., 15.22 ft. dist. Hereinafter described.~~

Ascend steep E. slope, through scattered timber.

2636.54

The ¼ sec. cor. of secs. 7 and 18, perpetuated in 1976 from the original evidence no longer in existence, by Duane I. Griffith, Professional Land Surveyor No. 644, and recorded as Survey No. 43-76 at the Union County Surveyor's Office, in LaGrande, Oregon, subsequently utilized in 1989, by Leland Lee Myers, Professional Land Surveyor No. 699, recorded as Survey No. 21-89 at the Union County Surveyor's Office in LaGrande, Oregon, monumented with an iron pipe, 1½ ins. diam., firmly set, projecting 16 ins. above the ground, in a mound of stone, 3 ft. base, to top, with brass cap mkd.

T 4 S R 35 E
S 7
1/4 ———
S 18
1976
PLS 644

T4S35J03

from which the accessories established by Myers in 1989

An iron rod, 5/8 in. diam., firmly set, flush with the surface of the ground, bears S. 86° 30' 00" E., 23.50 ft. dist., with a yellow plastic cap mkd. PLS 699.

An iron rod, 5/8 in. diam., firmly set, projecting 1 in. above the ground, bears N. 1° 30' 00" W., 15.80 ft. dist., no cap.

Corner is located in open, level land, and is beneath a barbed wire fence, bears N. and S.

The geographic position (NAD 1983 (CORS 96)) of this corner is:

Latitude: 45° 13' 33.060" N. Longitude: 118° 28' 31.684" W.

~~From the cor. of secs. 7, 8, 17, and 18.~~

~~N. 0° 42' 59" W., between secs. 7 and 8.~~

~~Over level land, through sparse timber.~~

1314.58

~~Point for S 1/16 sec. cor. of secs. 7 and 8, not monumented.~~