

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner has not been previously set.

DIAGRAM  
T4S R35E  
N1/16  
S17 | S16  
1989  
PLS 699

Description of corner evidence found:  
Corner is being set by this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 24" aluminum cap, marked as shown in the diagram, 24" in the ground in the braces of a fence rock jack, at a point as determined by the procedures set forth in the MANUAL OF INSTRUCTIONS FOR THE SURVEY OF PUBLIC LANDS for the subdivision of sections. Built a mound of rock to be 24" in diameter by 6" high around the monument.

No new bearing trees set because no trees are available.

No. 5 Rebar with a yellow plastic cap marked PLS 699 bears S85° 15'W, 19.0 feet.

No. 4 Rebar with a yellow plastic cap marked PLS 699 bears S1° 15'W, 15.4 feet.

Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between the SE and S quarter corners of Section 7 as shown on Union County Map of Survey No. 43-76.

Set steel fence posts 5 feet W and 5 feet S of the corner on the National Forest boundary lines. Attached Forest Boundary signs to each post and a Land Survey Monument sign to the W post.

<b>UNION COUNTY SURVEYOR</b>
Date Received <u>9-25-89</u>
Date Filed <u>9-25-89</u>
By <u>G. LANGLITZ</u>
File No. <u>184-89 R</u>

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on July 17, 1989, I established the corner as herein described.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON  
JULY 9, 1965  
LELAND LEE MYERS  
699

FILED

IN THE OFFICE OF THE UNION COUNTY SURVEYOR

THIS \_\_\_\_\_ DAY OF \_\_\_\_\_, 19\_\_\_\_

Union County Surveyor