


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner not previously established.



Description of corner evidence found:

None

**UNION COUNTY SURVEYOR**

---

Date Received 12-5-85

Date Filed 12-6-85

By G. LANGWITZ, DEPUTY

File No. 134-85 R

See map of survey dated November 1985.

Description of monument and accessories established to perpetuate the

original location of this corner: At position determined by survey, I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown 20" in the ground with surrounding mound of stone from which;

A 5/8"x30" iron pin with plastic cap marked BGA Survey Marker bears S22°W, 9.54 feet.


A 5/8"x30" iron pin with plastic cap marked BGA Survey Marker bears N66°W, 9.52 feet.

Set a steel fence post approximately 5 feet East with 54-9 and 54-2 sign attached.

Set a steel fence post approximately 5 feet South with a 54-2 sign attached.

Corner set 10/14/85

Witness: Greg Blackman, Rick Robinson, Stratton French



REGISTERED PROFESSIONAL LAND SURVEYOR

*Duane I. Griffith*

OREGON  
JULY 10, 1964  
DUANE I. GRIFFITH  
644

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....  
State of..... I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL) (DEPUTY)