


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

L-23

History of original corner establishment:
Corner not previously established.



Description of corner evidence found:

None

UNION COUNTY SURVEYOR

Date Received 12-5-85

Date Filed 12-6-85

By G. LANGLITZ, DEPUTY

File No. 138-85 R

See map of survey dated November 1985.

Description of monument and accessories established to perpetuate the original location of this corner: At position determined by survey, I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 18" in the ground with surrounding mound of stone 5 feet at the base to the top of the cap, from which:

A 5/8"x18" iron pin with plastic cap marked BGA Survey Marker, bears North, 5.17 feet, set next to steel fence post.


A 5/8"x18" iron pin with plastic cap marked BGA Survey Marker, bears West, 4.32 feet, set next to steel fence post.

Set steel fence post approximately 5 feet North with 54-9 and 54-2 sign attached.

Set steel fence post approximately 5 feet West with 54-2 sign attached.

Corner set 10/18/85

Witness: None



REGISTERED
PROFESSIONAL
LAND SURVEYOR

Handwritten signature of Duane I. Griffith

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by

(COUNTY OFFICIAL)

(DEPUTY)