## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner has not been previously set. DI AGRAH

T4S R35E

SE1/16+S17

1989 PLS 699

Description of corner evidence found: Corner is being set by this survey.

## UNION COUNTY SURVEYOR

Data Received 9-25-89

9-25-89

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 24" aluminum cap, marked as shown in the diagram, 14" in the ground to solid rock, at a point as determined by the procedures set forth in the MANUAL OF INSTRUCTIONS FOR THE SURVEY OF PUBLIC LANDS for the subdivision of sections. Built a mound of rock to be in diameter by 16" high around the monument, from which new BTs are:

15" Ponderosa pine bears #86°E, 320.4 feet scribed SE1/16 S17 BT 22" Ponderosa pine bears S45°E, 190.4 feet scribed SE1/16 S17 BT

Attached BT and Land Survey Monument signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between the SE and S% corners of Section 7 as shown on MOS 43-76, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet S of the corner with a Land Survey Monument

sign attached.

I,	Leland	L.	Myers	, P.	0.	Box	98,	Sumpter,	OR	97877.	
do	hereby	cer	tify	that	on	Jul	y 14	1, 1989,	Ie	stablis	hed
the	corner	as	here	in d	lesc	ribe	d.				

REGISTERED PROFESSIONAL AND SURVEYOR

> OREGON LELAND LEE MYERS

FILED

IN THE OFFICE OF THE Union COUNTY SURVEYOR

THIS \_\_\_\_ DAY OF \_

Union County Surveyor

USDA-FS Contract No. 04M3-8-6103