
History of original corner establishment:
Corner not previously established.



Description of corner evidence found:

None

UNION COUNTY SURVEYOR

Date Received 12-5-85

Date Filed 12-6-85

BY GLANYLIR DEPUTY

File No. 139-85 R

See map of survey dated November 1985.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey I set a 2½1x30" aluminum pipe with aluminum cap marked as shown, 13 inches in the ground with surrounding mound of stone 5 feet at the base to the top of the cap, from which:


A 24" Ponderosa Pine bears N37°W, 63.41 feet, marked SE 1/16 S14 BT.

A 22" Ponderosa Pine bears N $16^{\rm O}$ W, 62.70 feet, marked X BT

Set a steel fence post approximately 5 feet East with a 54-4 and 54-2 sign attached. Set a steel fence post approximately 5 feet South with 54-2 sign attached.

Corner Set 10/14/85

Witness: Greg Blackman, Stratton French



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1964

DUANE I. GRIFFITH
644

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	Country
for record on the day of	County of y that the within instrument was filed in this office
(COUNTY OFFICIAL)	by

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

M=20 Bk 2 Pg 9