

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner has not been previously set.

DIAGRAM

T4S R35E

E1/16 $\frac{S17}{S20}$

1989
PLS 699

Description of corner evidence found:
Corner is being set by this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 2 1/4" aluminum cap, marked as shown in the diagram, 14" in the ground to solid rock, at a point as determined by the procedures set forth in the MANUAL OF INSTRUCTIONS FOR THE SURVEY OF PUBLIC LANDS for the subdivision of sections. Built a mound of rock & earth to be 36" in diameter by 16" high around the monument.

No new bearing trees set because no trees are within the allowable limits.

No. 5 Rebar with yellow plastic cap stamped PLS 699 bears N2° 15'E, 26.2 feet.

No. 5 Rebar with yellow plastic cap stamped PLS 699 bears N89° 30'E, 20.5 feet.

Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between the SE and SW corners of Section 7 as shown on MOS 43-76.

Set a steel fence post 5 feet N of the corner with a Land Survey Monument sign attached.

UNION COUNTY SURVEYOR	
Date Received	<u>9-25-89</u>
Date Filed	<u>9-25-89</u>
By	<u>G. LANGRITZ</u>
File No.	<u>191-89 R</u>

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on July 14, 1989, I established the corner as herein described.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland L. Myers
OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Union COUNTY SURVEYOR
THIS ____ DAY OF _____, 19__

Union County Surveyor