

History of original corner establishment:
Corner not previously established.



Description of corner evidence found:

None



See map of survey dated November 1985.

Description of monument and accessories I established to perpetuate the


original location of this corner: At position determined by survey I set a 2½1x301 aluminum pipe with aluminum cap marked as shown, 28 inches in the ground from which:

A 16" Tamarack bears \$23°E, 49.60 feet, marked E 1/16 \$23 BT

A 10" Douglas Fir bears N44 $^{\rm O}$ N, 20.29 feet, marked E 1/16 S14 BT

Set a steel fence post approximately 5 feet North with 54-4 and 54-2 sign attached. Set a steel fence post approximately 5 feet West with 54-2 sign attached.

Corner set 10/14/85 Witness: Greg Blackman, Rick Robinson, Stratton French



REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1964

DUANE I. GRIFFITH
644

Brass washer nailed to BT blaze.
Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	County of
State of / he	ereby certify that the within instrument was filed in this office
for record on the day of	, 19
	by
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276