


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.



Description of corner evidence found:

None

UNION COUNTY SURVEYOR

Date Received 12-5-85

Date Filed 12-6-85

By G. LANGRIZ, DEPUTY

File No. 149-85R

See map of survey dated November 1985.

Description of monument and accessories I established to perpetuate the original location of this corner: At position determined by survey I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 12 inches in the ground with surrounding mound of stone; 5 foot base to top of cap, from which:

A 5/8"x30" iron pin with plastic cap marked BGA Survey Marker bears S34°W, 44.13 feet.


A 5/8"x30" iron pin with plastic cap marked BGA Survey Marker bears N65°W, 29.28 feet.

Set a steel fence post approximately 5 feet North with a 54-9 and 54-2 sign attached.

Set a steel fence post approximately 5 feet South with a 54-2 sign attached.

Corner set 10/15/85

Witness: Greg Blackman, Stratton French



REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....
State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....
..... by
(COUNTY OFFICIAL) (DEPUTY)