

History of original corner establishment: Corner not previously established.



Description of corner evidence found:

None



See map of survey dated November 1985.

Description of monument and accessories I established to perpetuate the

original location of this corner: Corner position falls in deep wash, I therefore set a witness corner S 0°38'28'E, along the North South center of section line, 25 feet. The monument being a 2½'x30" aluminum pipe with aluminum cap marked as shown, 28 inches in the ground with surrounding mound of stone, from which:


An 18" Douglas Fir bears West 4.75 feet, marked X BT

An 11" Douglas Fir bears N12°W, 17.50 feet, marked XX BT

Set a stee! fence post approximately 5 feet North with a 54-9 sign attached.

Corner set 10/17/85
Witness: Rick Robinson, Stratton French





Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	County of
State of,	I hereby certify that the within instrument was filed in this office
for record on the day of	, 19
	by
	LL (DEPUTY)

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276