


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.



Description of corner evidence found:

None

UNION COUNTY SURVEYOR

Date Received 12-5-85
 Date Filed 12-6-85
 By G. LANGRISH, DEPUTY
 File No. 152-85 R

See map of survey dated November 1985.

Description of monument and accessories I established to perpetuate the original location of this corner: At position determined by survey, I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 17 inches in the ground with surrounding mound of stone 5 feet base to top of cap, from which;

A 5/8"x18" iron pin with poastic cap marked BGA Survey Marker bears S52°E., 6.96 feet

A 5/8"x18" iron pin with plastic cap marked BGA Survey Marker bears S21°W, 7.06 feet.


Set a steel fence post approximately 5 feet South with 54-9 sign attached.

Corner set 10/15/85

Witness: Rick Robinson

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 10, 1964
DUANE I. GRIFFITH
644



Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 19.....

..... by
(COUNTY OFFICIAL) (DEPUTY)