


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner established by Rufus S. Moore under General Land office contract no. 451, dated June 12, 1882. Surveyor General Records states: Set a basalt stone 20"x10"x8", 15 inches in the ground for 1/4 section corner marked 1/4 on W face and raised a mound of stone alongside, pits impracticable.



No record of subsequent remonumentation was found in County Records.

Description of corner evidence found:

NONE

UNION COUNTY SURVEYOR	
Date Received	<u>12-5-85</u>
Date Filed	<u>12-6-85</u>
By	<u>G. LANGLITZ, DEPUTY</u>
File No.	<u>153-85 R</u>

See map of survey dated November 1985.

Description of monument and accessories I established to perpetuate the original location of this corner: At proportionate distance I set a 2 1/2"x30" aluminum pipe with aluminum cap marked as shown, 20" in the ground in surrounding mound of stone, from which:

A 5/8"x30" iron pin with plastic cap marked BGA Survey Marker bears N41°E 7.62 FT.


A 5/8"x30" iron pin with plastic cap marked BGA Survey Marker bears N57°W, 8.14 ft.

Set a steel fence post approximately 5 feet North with a 54-4 and 54-2 sign attached.

Set a steel fence post approximately 5 feet South with 54-2 sign attached.

Corner set 10/19/85

Witness: Greg Blackman, Rick Robinson



**REGISTERED PROFESSIONAL LAND SURVEYOR**

*Duane I. Griffith*  
OREGON  
JULY 10, 1964  
**DUANE I. GRIFFITH**  
644

Brass washer nailed to RT blaze. Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of..... County of.....  
State of....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....  
..... by .....  
(COUNTY OFFICIAL) (DEPUTY)