

History of original corner establishment:
Corner not previously established.



Description of corner evidence found:

None



See map of survey dated November 1985.

Description of monument and accessories I established to perpetuate the


original location of this corner: At position determined by survey I set a  $2^{1}2^{1}x30^{11}$  aluminum pipe with aluminum cap marked as shown, 20 inches in the ground with surrounding mound of stone from which:

A 3/4"x18" iron pin with plastic cap marked BGA Survey Marker bears N42°E, 7.54 feet.

A 3/4"x18" iron pin with plastic cap marked BGA Survey Marker bears \$33°E, 6.83 feet.

Set a stee# fence post approximately 5 feet East with a 54-9 sign attached.

Corner set 10/15/85 Witness: Rick Robinson



PROFESSIONAL LAND SURVEYOR

OREGON
JULY 10, 1964

DUANE I. GRIFFITH

REGISTERED

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	v of
for record on the day of	vithin instrument was filed in this office . 19
(COUNTY OFFICIAL)	(DEDIM)

Form R6-7100-57 (9/71)

☆U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276