

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Corner not previously established.



Description of corner evidence found:

tione



See map of survey dated November 1985.

Description of monument and accessories I established to perpetuate the

original location of this corner: At position determined by survey I set a 2½ x30" aluminum pipe with aluminum cap marked as shown 18 inches in the ground with surrounding mound of stone 4 foot base to top of cap, from which:

A 5/8'x30" iron pin with plastic cap marked BGA Survey Marker bears North 5.14 feet.


A 5/8"x30" iron pin with plastic cap marked BGA Survey Marker bears West 4.67 feet.

Above references set next to steel fence posts with signs .

Set steel fence post approximately 5 feet North with 54-9 and 54-2 sign attached. Set steel fence post approximately 5 feet West with 54-2 sign attached.

Corner set 10/15/85 Witness: Greg Blackman

> REGISTERED PROFESSIONAL AND SURVEYOR



OREGON
JULY 10, 1964
DUANE I. GRIFFITH

Brass washer nailed to BT blaze. Used steel tape and magnetic compass with 20° East declination. Measured to 50d spike set in right side of tree when facing tree, unless otherwise stated.

Office of	County of
State of , I hereby ce	ertify that the within instrument was filed in this office
for record on the day of	, 19
	by
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276