## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment: Record of the original survey by Herman D. Gradon, Contract No. 452, 1882, states:

Set a basalt stone, 14x8x6 in. 9 ins. in the ground for cor. to secs. 7, 8, 17 and 18, marked with 4 notches on S and 5 notches on E edges, from which:

A Pine 10 ins. diam. bears  $\rm S25^{0}E$  29 lks., dist., marked T4S R36E S17 BT.

A Pine 10 ins. diam. bears  $\rm S12^{0}W$  25 lks. dist., marked T4S R36E S18 BT.

No other trees within limits and raised a mound of stone alongside.

Index File No. J-5

DIAGR	AM
T4S	R36E
7_18	-8 17

T4S R36E

S18 | S17 PLS 1099

1980

S8

S7

 $\begin{array}{ll} \textbf{Description of corner evidence found:} & \underline{Found:} & \textbf{No trace remains of the original corner stone} \\ \textbf{Or stone mound.} \end{array}$ 

We establish the  $\underline{\text{True Corner Point}}$  in the following relationship with the remains of the original bearing trees:

The remains of an orig. 10" Pine, now down with only the scribed portion remaining intact, scribing "T4S R36E S17 BT" visible on a unhealed double blaze, the root hole of which bears S25°E 19.1 ft., and an orig. 10" now 24" Ponderosa Pine, alive, well healed and now partially opened, no marks visible bears S12°W 16.5 ft.

Description of monument and accessories I established to perpetuate the original location of this corner: At the <u>True Corner Point</u>, we set a 2"x30" Galvanized Iron Pipe, 20 in. in the ground on a steep east slope approx. 40' North of a small draw, with brass cap attached, marked:

From which we mark new bearing trees.

A 6" Douglas Fir, scribed "T4S R36E S17 BT" on a double blaze bears  ${\rm S38^0E}$  5.6 ft.

A 14" Ponderosa Pine, scribed "T4S R36E S8 BT" on a double blaze bears N31 $^{12}{}^{0}$ E 81.2 ft.

A 7" Ponderosa Pine, scribed "T4S R36E S7 BT" on a double blaze bears N44°W 43.7 ft.

Attached brass washer stamped "LS 1099" on lower blaze of new BTs. Placed steel fence post 5 ft. N or corner with sign 54-4. Attached signs and painted BTs per Standard Specifications for Cadastral Survey, U.S.F.S., Region 6, October, 1979.

Compass Declination:  $20^{\circ}$  East.

I hereby certify that the above described corner and/or accessories was established on August 21, 1980.

Witr	tness: Mike Wagoner
County C	REGISTERED PROFESSIONAL LAND SURVEYOR
Office of County Surveyor County of Unstate of Oregon , I hereby certify that the within instrum	ment was filed in this office
(COUNTY OFFICIAL)	I OREGON O
Form R6-7100-57 (9/71)	
1	ceived \$\preceq\$

Date Filed

File No. 471-84 R