


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not established during original survey.

Index File No. L-3



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner

At surveyed point set 2 1/2" x 30" galvanized pipe with brass cap stamped:  
Set pipe 22" in ground with mound of stone to cap.

New BT's,

A Ponderosa Pine 11" dia. bears S34°W, 16.2 ft scribed C 1/4 S18 BT.

A Ponderosa Pine 10" dia. bears S26°E, 27.3 ft scribed C 1/4 S18 BT.


Attached 54-9 sign to metal post 5' East of cor. Attached 54-3 & 54-9 signs to both BT's.  
Attached brass washer stamped LS 1099 to foot blaze of both BT's. Painted blazes & 6" band around both BT's, red.

Corner falls on West slope 100' South of large clearing and approx. 145' West of forest road.

Compass Declination: 18° 15' East

Witnesses: Rodger Orton  
Alan Hanley

I hereby certify that the above described corner and/or accessories was established on October 20, 1980.



REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Gary L. Langlitz*  
OREGON  
JULY 22, 1977  
GARY L. LANGLITZ  
1099

Office of County Surveyor County of Union  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the \_\_\_\_\_ day of \_\_\_\_\_  
(COUNTY OFFICIAL) by \_\_\_\_\_ (DEPUTY)

**UNION COUNTY SURVEYOR**

Date Received \_\_\_\_\_

Date Filed NOV 29 1980

By \_\_\_\_\_

File No. 474-84R