


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No. M-5

History of original corner establishment:

Not established during original survey




Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

At surveyed point we set a 2"x30" Galvanized Iron Pipe, 18" in the ground in mound of stone to top, with brass cap attached,  
Marked:



From which:

A 7" Douglas Fir, scribed "S 1/16 S 17 BT" on a double blaze bears S51°E 75.8 ft.

A 10" Douglas Fir, scribed "S1/16 S18 BT" on a double blaze bears S40°W 61.5 ft.

Attached brass washer, maked "LS1099" to lower blaze of each bearing tree.

Placed steel fenceposts approximately 5 ft. West and South of the monument with signs 54-2 and 54-9 attached.

Attached signs and painted BT's per Standard Specifications For Cadastral Survey, U.S.F.S. Region 6, Oct., 1979.

Compass declination: 18° 15' East

Witnesses: Glenn Wagoner  
              Alan Hanley  
              Millard Wyatt

I hereby certify that the above described corner and/or accessories was established on October 16, 1980.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Gary L. Langlitz*

OREGON  
JULY 22, 1977  
GARY L. LANGLITZ  
1099

Office of.....County..Surveyor..... County of.....Union.....  
State of.....Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19.....

..... by .....  
(COUNTY OFFICIAL)

**DEPUTY COUNTY SURVEYOR**

.....

Date Filed \_\_\_\_\_

By \_\_\_\_\_

File No. 478-84 R