CERTIFIED RECORD OF LAND CONNER MONUMENTATION

History of original corner establishme	ent
--	-----

Corner extablished by General Land Office Contract survey.

The original notes state;
West between sections 15 and 22;
40.05 ch. set a post 3' long 3" square, 24" in ground for \$\frac{1}{4}\$ corfrom which;
Pine 12" in diam bears N80°E 19 lks dist marked \$\frac{1}{4}\$SBT;
Pine 14" in diam bears \$70°W 19 lks dist marked \$\frac{1}{4}\$SBT;

N-15
diagram T4S R36EWM
<u>S15</u> S22
•

Description of corner evidence found:

Found 15" pine with scribe in section 15;

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 30 galvanized pipe with and eight inch plate welded to bottom and a bronze cap on top. The hole was back filled with stone and tamped soil;

‡ COR T4S R36E

I stamped the disk

S15 S22 ORE LIC 381 1970

From the monument the original bearing tree was;
Pine 15" in diam bears N80°E 19 lks dist. marked †SBT;
I established the following new bearing tree;
Ponderosa pine 15" in diam bears S20°W at a distance of 22 ft.
scribed †SBT; The distance measured to center of tree
on the level. I placed bearing tree signs on both old and new
bearing trees and painted stripe around trees. I placed a steel
54-4 attachednear the corner and placed USFS boundary sign on the
USFS land to south

bearing trees and painted stripe around trees. I placed a steel fence post with USFS sign 54-4 attachednear the corner and placed USFS boundary sign on the post indicating USFS land to south.

Office of County surveyor County of Union	URBON COUNTY
State of Oregon , I hereby certify that the within instrument was file	ed in this office
for record on the 6 day of August 19 70, or 2. o'clock	P.m., (signed)
(COUNTY OFFICIAL)	BeterReceived
	Date Filed
	Ву
	File No. 490-84R

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Refer to Certified Record of Land Corner Monumentation 25-70A by James G. Voelz PLS 381, as recorded in the Office of Union County Surveyor, August 6, 1970.

Index	File No. N-15			
DIAGRAM				
T4S	R36E			
15 22 1/4				

Description of corner evidence found:

Found: A 2" Iron Pipe, firmly set, extending 10" above ground, with brass cap attached, marked:

From which the only remaining original BT (Gradon, 1882). An orig. 12" Pine, now 22", alive, with scribing "1/4 S" and "US" brand visible on a previously opened blaze, bears N80°E, 12.5 ft., (Rec. N80°E 19 lks.). And a Bearing Tree marked by Voelz, 1970,

A 15" Ponderosa Pine, now broken, with a stump remaining, scribing "1/4 S BT" visible on an unhealed double blaze, bears $\rm S1/2^0E$ 22.0 ft. (Rec. $\rm S20^0W$ 22 ft.) Note: The BT tag reads $\rm N2^0E$.

1/4 COR. T4S R36E S15 S22 Ore. Lic. 381

Description of monument and accessories I established to perpetuate the original location of this corner: We mark a new BT:

A 6" Larch, scribed "1/4 S22 BT" on a double blaze bears $\rm S32^{12}_{20}W$ 47.2 ft., with brass washer, marked "LS 1099" attached to lower blaze.

Placed Voelz fence post approx. 3 ft. East of the monument with signs 54-2 and 54-4 signs attached.

Attached signs and painted BTs. per Standard Specifications for Cadastral Survey, U.S.F.S., Region 6, Oct., 1979.

Compass Declination: 20° East.

I hereby certify that the above described corner and/or accessories was established on October 16, 1980.

File No 489-84 R

Witness: John Curtiss

PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 22, 1977
GARY L. LANGLITZ
1099

Office of County Surveyor County Surveyor County State of Oregon I hereby certify that	t the within instrument was filed in	this office
byby	UNION COUNTY	
(COUNTY OFFICIAL)	(DEPUTY)	SURVEYOR
orm R6-7100-57 (9/71)		Date Received
		Date Filed