


26-70A

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by General Land Office contract survey
The original notes state:
North between sections 21 and 22.
Through timber.
3.00 Dry bed of creek course Northwest
40.00 Set a basalt stone 18 x 12 x 6", 12" in ground for $\frac{1}{4}$ section corner marked $\frac{1}{4}$ on West face from which;
Tamarack 22" dia bears S70°E 11 lks dist marked $\frac{1}{4}$ SBT
Fir 12" dia bears N60°W 19 lks dist marked $\frac{1}{4}$ SBT.

P. 13



Description of corner evidence found:


Found, in section 22, an 18" tamarack with scribe, in good shape.

Description of monument and accessories I established to perpetuate the original location of this corner

At the position of the corner I set a 30" galvanized pipe with an eight inch plate welded to bottom and a bronze cap on top. The hole was back filled with stone and tamped soil.

I stamped the disk.

From the monument the original bearing tree was;
Tamarack 18" dia S70°E 11 lks dist marked $\frac{1}{4}$ SBT.
I established the following new bearing tree;
White Fir 8" dia N53°W at a distance of 9.8 ft. and scribed $\frac{1}{4}$ SBT.
The distance measured to center of respective trees on level. I placed bearing tree signs on both the old and new bearing trees and painted stripe around the trees. I placed a steel fence post with USFS sign 54-4 attached near the corner.



Office of County Surveyor County of Union

State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 6th day of August, 1970, at 5 o'clock P. m., (signed) James R. [Signature] County Surveyor (COUNTY OFFICIAL) by [Signature] (DEPUTY)

UNION COUNTY SURVEYOR

Date Received _____

Date Filed _____

By _____

File No. 494-84R